
♦DATALOGIC™

BA100

DIN RAIL MOUNTING ADAPTER KIT INSTRUCTION MANUAL



- Attach the DIN Rail adapters to the back of the CBX or SC4000 paying attention to the Left (L) and Right (R) markings.
- 2. Insert and tighten the screws.
- 3. Snap the assembly onto the DIN Rails.


♦DATALOGIC

BA200

BOSCH FRAME MOUNTING ADAPTER KIT INSTRUCTION MANUAL

CBX or SC4000

- Insert the two bolts behind the CBX or SC4000.
- Place the assembly onto the Bosch profile so that the bolts enter the profile channel and then rotate the bolts <u>clockwise</u> 90° so that they lock into place.
- Install the two small diameter washers and fasten the two nuts until tight.



QL

- Place the two large diameter washers onto the two bolts and then insert them behind the OI
- Place the assembly onto the Bosch profile so that the bolts enter the profile channel and then rotate the bolts <u>clockwise</u> 90° so that they lock into place.
- Install the two small diameter washers and fasten the two nuts until tight.

